



Figure three: Chest x-ray showing a dual chamber pacemaker with one lead in the position of the right atrium and a lead positioned within the left side of the cardiac silhouette suggesting lead malposition (arrow).