



Figure 2. Receiver-operating characteristic (ROC) curve analysis. prediction of right ventricular failure after left ventricular assist device (LVAD) implantation. Area under the curve (AUC) 0.86 for Hemodynamic Index.